This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Sheets of Drawings: 1 of 10




Applu No.: 09/866,770

Ritle: Determining the Effects of new Types of Impairments on Perceived...

Inventors: Hardy Confirmation No.: 6275

Sheets of Drawings: 2 of 10



Appin No.: 09/866,770
Title: Determining the Effects of new Types of Impairments on Perceived...

Inventors: Hardy

Confirmation No.: 6275 Sheets of Drawings: 3 of 10




FIG. 3A



FIG. 3B



FIG. 3C

Sheets of Drawings: 4 of 10 4/10 Felephone PSTN Gateway Gateway Detection Circuitry Router Router FIG. 4 Router \$ Gateway PSTN

Telephone

Docket No.: RIC98014P2
Appln No.: 09/866,770
Title: Determining the Effects of new Types of Impairments on Perceived...
Inventors: Hardy
Confirmation No.: 6275

Shects of Drawings: 5 of 10





FIG. 5




and Packet Delay Combination

Appln No.: 09/866,770
Title: Determining the Effects of new Types of Impairments on Perceived....

Inventors: Hardy Confirmation No.: 6275

Sheets of Drawings: 2 of 10



Sheets of Drawings: 8 of 10





FIG. 8

Sheets of Drawings: 9 of 10



Appln No.: 09/866,770
Title: Determining the Effects of new Types of Impairments on Perceived...

Inventors: Hardy Confirmation No.: 6275

